



Site 320 - Photo 05 - 10,000-gallon heating oil UST sign (Gold Acres Apartments)



Site 320 - Photo 06 - 10,000-gallon heating oil UST vent pipe (Gold Acres Apartments)



Site 320 - Photo 07 - Boiler (Gold Acres Apartments)



Site 320 - Photo 08 - Boiler room (Gold Acres Apartments)





Site 320 - Photo 09 - Floor drain in boiler room (Gold Acres Apartments)



Site 320 - Photo 10 - Floor drain in boiler room (Gold Acres Apartments)



Site 320 - Photo 11 - Staining at base of boiler room fuel filter (Gold Acres Apartments)



Site 320 - Photo 12 - Staining at base of boiler room piping (Gold Acres Apartments)





Site 320 - Photo 13 - Heating oil supply lines (Gold Acres Apartments)



Site 320 - Photo 14 - Apartment buildings (Pine Ridge Apartments)



Site 320 - Photo 15 - 10,000-gallon heating oil UST (Pine Ridge Apartments)



Site 320 - Photo 16 - 10,000-gallon heating oil UST registration (Pine Ridge Apartments)





Site 320 - Photo 17 - 10,000-gallon heating oil UST label (Pine Ridge Apartments)



Site 320 - Photo 18 - 10,000-gallon UST vent pipe (Pine Ridge Apartments)




Site 320 - Photo 19 - Staining at base of boiler room piping #1 (Pine Ridge Apartments)



Site 320 - Photo 20 - Staining at base of boiler room piping #2 (Pine Ridge Apartments)





Site 320 - Photo 21 - Boiler (Pine Ridge Apartments)



Site 320 - Photo 22 - Boiler room (Pine Ridge Apartments)



Site 320 - Photo 23 - Floor drain in boiler room (Pine Ridge Apartments)



Site 320 - Photo 24 - Heating oil supply lines (Pine Ridge Apartments)





Site 320 - Photo 25 - Natural gas meter (Pine Ridge Apartments)



Site 320 - Photo 26 - Pole-mounted transformers



Site 321 - Photo 01 - Public park (Long Branch)



Site 321 - Photo 02 - Pole-mounted transformer





Site 322 - Photo 01 - Long Branch Trail



Site 323 - Photo 01 - Long Branch Community Center and Pool



Site 323 - Photo 02 - Pad-mounted transformer #1



Site 323 - Photo 03 - Pad-mounted transformer #2





Site 323 - Photo 04 - HVAC



Site 323 - Photo 05 - Natural gas meter



Site 324 - Photo 01 - Business (Mile Glass Replacement)



Site 325 - Photo 01 - Multiple businesses (restaurants and hair salon)





Site 325 - Photo 02 - Natural gas meter



Site 326 - Photo 01 - Office building (Dental Center)



Site 327 - Photo 01 - Apartment buildings (Foxhill Apartments)



Site 327 - Photo 02 - Apartment buildings (Foxhill Apartments)





Site 327 - Photo 03 - Pole-mounted transformer



Site 327 - Photo 04 - Natural gas meter



Site 328 - Photo 01 - Gas station (Exxon)



Site 328 - Photo 02 - UST tank field





Site 328 - Photo 03 - Oil and water separator #1



Site 328 - Photo 04 - Floor drains inside car wash



Site 328 - Photo 05 - Oil and water separator #2



Site 328 - Photo 06 - Abandoned Monitoring well





Site 329 - Photo 01 - Auto repair facility (Tire Depot Express)



Site 329 - Photo 02 - Pole-mounted transformer



Site 330 - Photo 01 - Laundromat and carwash



Site 330 - Photo 02 - Laundromat and carwash





Site 331 - Photo 01 - Gas station and convenience store (7-11)



Site 331 - Photo 02 - UST tank field



Site 331 - Photo 03 - Monitoring well



Site 331 - Photo 04 - Pole-mounted transformer





Site 332 - Photo 01 - Auto repair facility (Precision Tune Auto Care)



Site 332 - Photo 02 - Used oil burner



Site 332 - Photo 03 - 275-gallon used oil AST



Site 332 - Photo 04 - 275-gallon lube oil AST





Site 332 - Photo 05 - Empty 55-gallon drum and surficial staining



Site 332 - Photo 06 - Surficial staining



Site 332 - Photo 07 - 55-gallon drums of lube oil and used antifreeze



Site 332 - Photo 08 - Lube oil drum #1





Site 332 - Photo 09 - Lube oil drum #2



Site 332 - Photo 10 - Lube oil drum #3



Site 332 - Photo 11 - Unused 275-gallon heating oil AST



Site 332 - Photo 12 - Removed oil and water separator





Site 333 - Photo 01 - Shopping center



Site 333 - Photo 02 - Pad-mounted transformer



Site 333 - Photo 03 - Natural gas meter



Site 334 - Photo 01 - Residence





Site 335 - Photo 01 - Residence



Site 336 - Photo 01 - Abandoned business



Site 337 - Photo 01 - Public park



Site 337 - Photo 02 - Public park





Site 337 - Photo 03 - Parking at public park



Site 337 - Photo 04 - Public park



Site 338 - Photo 01 - Casa of Maryland Medical Office



Site 338 - Photo 02 - Natural gas meter





Site 339 - Photo 01 - Apartments (University Manor)



Site 339 - Photo 02 - Apartments (University Manor)



Site 339 - Photo 03 - Pad-mounted transformer #1



Site 339 - Photo 04 - Pad-mounted transformer #2





Site 340 - Photo 01 - Residence



Site 341 - Photo 01 - Pad-mounted transformer



Site 341 - Photo 01 - Townhouse neighborhood



Site 342 - Photo 01 - Residence





Site 342 - Photo 02 - Pole-mounted transformer



Site 343 - Photo 01 - Residence



Site 344 - Photo 01 - Residence



Site 345 - Photo 01 - Residence





Site 345 - Photo 02 - Pole-mounted transformer



Site 346 - Photo 01 - Residence



Site 347 - Photo 01 - Residence



Site 348 - Photo 01 - Office building





Site 348 - Photo 02 - Pad-mounted transformer



Site 349 - Photo 01 - Residence



Site 350 - Photo 01 - Residence



Site 351 - Photo 01 - Residence





Site 352 - Photo 01 - Residence



Site 353 - Photo 01 - Residence



Site 354 - Photo 01 - Residence



Site 355 - Photo 01 - Residence





Site 356 - Photo 01 - Residence



Site 357 - Photo 01 - Residence



Site 358 - Photo 01 - Residence



Site 359 - Photo 01 - Residence





Site 360 - Photo 01 - Residence



Site 361 - Photo 01 - Residence



Site 361 - Photo 02 - Pole-mounted transformer



Site 362 - Photo 01 - Residence





Site 363 - Photo 01 - Residence



Site 364 - Photo 01 - Residence



Site 364 - Photo 02 - Natural gas shutoff



Site 365 - Photo 01 - Residence





Site 366 - Photo 01 - Residence



Site 367 - Photo 01 - Residence



Site 368 - Photo 01 - Church



Site 368 - Photo 02 - Pole-mounted transformer





Site 369 - Photo 01 - Gas station (Shell)



Site 369 - Photo 02 - UST tank field



Site 369 - Photo 03 - Waste oil UST



Site 369 - Photo 04 - 55-gallon drum of used antifreeze





Site 369 - Photo 05 - 55-gallon drums of used antifreeze



Site 369 - Photo 06 - UST vent pipes



Site 369 - Photo 07 - UST tank field label



Site 370 - Photo 01 - Shopping center





Site 370 - Photo 02 - Pole-mounted transformer



Site 371 - Photo 01 - Residence



Site 372 - Photo 01 - Residence



Site 373 - Photo 01 - Residence





Site 373 - Photo 02 - Pole-mounted transformer



Site 374 - Photo 01 - Residence



Site 375 - Photo 01 - Apartment buildings (Langley Garden)



Site 375 - Photo 02 - Apartment buildings (University Landing)





Site 375 - Photo 03 - Apartment buildings (University Landing)



Site 375 - Photo 04 - Apartment buildings (University Landing)



Site 375 - Photo 05 - Pad-mounted transformer #1



Site 375 - Photo 06 - Pad-mounted transformer #2





Site 375 - Photo 07 - Pole-mounted transformer #1



Site 375 - Photo 08 - Pole-mounted transformer #2



Site 375 - Photo 09 - Pole-mounted transformer #3



Site 375 - Photo 10 - Pole-mounted transformer #4





Site 375 - Photo 11 - Grass lot



Site 376 - Photo 01 - Apartment buildings



Site 376 - Photo 02 - Pole-mounted transformer



Site 376 - Photo 03 - Gas shutoff





Site 377 - Photo 01 - Apartment building



Site 377 - Photo 02 - Pole-mounted transformer



Site 377 - Photo 03 - Natural gas meter



Site 378 - Photo 01 - Office building





Site 379 - Photo 01 - Office building



Site 380 - Photo 01 - Dentist office



Site 381 - Photo 01 - Commercial building



Site 382 - Photo 01 - Office building





Site 383 - Photo 01 - Office building



Site 384 - Photo 01 - Multiple businesses



Site 384 - Photo 02 - Pole-mounted transformer



Site 385 - Photo 01 - Business (Grocery Store)





Site 385 - Photo 02 - Pad-mounted transformer



Site 385 - Photo 03 - Oil and water separator



Site 386 - Photo 01 - Shopping center



Site 386 - Photo 02 - Shopping center





Site 386 - Photo 03 - Dry cleaning facility (BZ Cleaners)



Site 386 - Photo 04 - Pole-mounted transformer



Site 387 - Photo 01 - Shopping center



Site 387 - Photo 02 - Shopping center





Site 387 - Photo 03 - Bank (Bank of America)



Site 387 - Photo 04 - Restaurant (Taco Bell)



Site 388 - Photo 01 - Shopping center



Site 388 - Photo 02 - Parking lot





Site 388 - Photo 03 - Pad-mounted transformer



Site 388 - Photo 04 - Restaurant (McDonald's)



Site 388 - Photo 05 - Pad-mounted transformer



Site 388 - Photo 06 - Oil and water separator





Site 389 - Photo 01 - Fueling tank field #1



Site 389 - Photo 01 - Gas station (Exxon)



Site 389 - Photo 02 - Fueling tank field #2



Site 389 - Photo 03 - Heating oil UST





Site 389 - Photo 04 - Heating oil UST fill pipe



Site 389 - Photo 05 - Used oil container



Site 389 - Photo 06 - 55-gallon drum of used oil



Site 389 - Photo 07 - 55-gallon drum of anti-freeze drum





Site 389 - Photo 08 - Oil and water separator



Site 389 - Photo 09 - Abandoned Monitoring well #1



Site 389 - Photo 10 - Abandoned Monitoring well #2



Site 390 - Photo 01 - Business (7-11 Convenience Store)





Site 391 - Photo 01 - Shopping center



Site 391 - Photo 02 - Shopping center



Site 391 - Photo 03 - 55-gallon drums of cooking grease



Site 391 - Photo 04 - Pole-mounted transformer #1





Site 391 - Photo 05 - Pole-mounted transformer #2



Site 392 - Photo 01 - Business (Walgreens)



Site 392 - Photo 02 - Propane cylinder storage



Site 393 - Photo 01 - Shopping center





Site 393 - Photo 02 - Pad-mounted transformer



Site 394 - Photo 01 - E-Z Storage facility



Site 394 - Photo 02 - Pad-mounted transformer



Site 394 - Photo 03 - Pole-mounted transformers





Site 395 - Photo 01 - Restaurant



Site 395 - Photo 02 - Pole-mounted transformer



Site 395 - Photo 03 - Oil and water separator



Site 396 - Photo 01 - Apartment buildings (Liberty Place)






Site 396 - Photo 02 - Heating oil UST



Site 396 - Photo 03 - Heating oil UST vent pipe



Site 396 - Photo 04 - Heating oil UST staining



Site 396 - Photo 05 - Boiler room





Site 396 - Photo 06 - Floor drain in boiler room



Site 396 - Photo 07 - Former coal boiler



Site 396 - Photo 08 - Natural gas meter



Site 397 - Photo 01 - Apartment buildings (Bedford Station)





Site 397 - Photo 02 - Old heating oil UST



Site 397 - Photo 03 - Heating oil UST fill pipe



Site 397 - Photo 04 - Smoke stack #1 at boiler room



Site 397 - Photo 05 - Smoke stack #2 at boiler room





Site 397 - Photo 06 - Boiler room



Site 397 - Photo 07 - 55-gallon drum of boiler water treatment



Site 397 - Photo 08 - Boiler room #2



Site 397 - Photo 09 - Pole-mounted transformer





Site 397 - Photo 10 - Natural gas meter #1



Site 397 - Photo 11 - Natural gas meter #2



Site 398 - Photo 01 - Shopping center



Site 398 - Photo 02 - Pad-mounted transformer





Site 398 - Photo 03 - Pole-mounted transformer



Site 399 - Photo 01 - Shopping center



Site 399 - Photo 02 - Pad-mounted transformer



Site 399 - Photo 03 - Pole-mounted transformer





Site 400 - Photo 01 - Shopping center



Site 400 - Photo 02 - Business (Autozone)



Site 400 - Photo 03 - 200-gallon waste oil AST



Site 400 - Photo 04 - Open monitoring well





Site 400 - Photo 05 - Natural gas meter



Site 401 - Photo 01 - Shopping center (University Place)



Site 401 - Photo 02 - Pole-mounted transformers




Site 401 - Photo 03 - Pole-mounted transformer





Site 401 - Photo 04 - Phone junction box



Site 401 - Photo 05 - Phone junction box



Site 402 - Photo 01 - Multiple businesses (furniture store and check cashing)



Site 402 - Photo 02 - Survey monument





Site 403 - Photo 01 - Restaurant



Site 403 - Photo 02 - Pole-mounted transformer



Site 404 - Photo 01 - Auto repair facility (Pep Boys)



Site 405 - Photo 01 - Business (Tick Tock Liquors)










Site 406 - Photo 04 - Waste oil ASTs



Site 406 - Photo 05 - Left waste oil AST label



Site 406 - Photo 06 - Right waste oil AST label




Site 406 - Photo 07 - Used anti-freeze drums





Site 407 - Photo 01 - Multiple businesses



Site 407 - Photo 02 - Pole-mounted transformer



Site 408 - Photo 01 - Restaurant



Site 409 - Photo 01 - Gas station (Exxon)





Site 409 - Photo 02 - UST tank field



Site 409 - Photo 03 - UST tank field



Site 409 - Photo 04 - UST tank field



Site 409 - Photo 05 - Oil and water separator





Site 409 - Photo 06 - Oil and water separator clean out



Site 409 - Photo 07 - Car wash floor drains



Site 409 - Photo 08 - Oil and water separator in car wash area



Site 409 - Photo 09 - Abandoned monitoring well





Site 409 - Photo 10 - Natural gas meter



Site 410 - Photo 01 - Business (laundromat)



Site 410 - Photo 02 - Multiple businesses (laundromat, insurance, and check cashing)



Site 410 - Photo 03 - Pole-mounted transformer





Site 411 - Photo 01 - Auto repair facility



Site 411 - Photo 02 - Tank Field



Site 411 - Photo 03 - Vent pipes



Site 411 - Photo 04 - 300-gallon used oil AST






Site 411 - Photo 05 - 300-gallon used oil AST



Site 411 - Photo 06 - 200-gallon AST



Site 411 - Photo 07 - 200-gallon heating oil AST



Site 412 - Photo 01 - Strip mall





Site 412 - Photo 02 - Restaurant



Site 412 - Photo 03 - Business (liquor store and grocery)



Site 412 - Photo 04 - Pole-mounted transformer #1



Site 412 - Photo 05 - Pole-mounted transformer #2





Site 412 - Photo 06 - Pole-mounted transformer #3



Site 412 - Photo 07 - Pole-mounted transformer #4



Site 412 - Photo 08 - Natural gas meter #1



Site 412 - Photo 09 - Natural gas meter #2





Site 412 - Photo 10 - Natural gas meter #3



Site 412 - Photo 11 - Natural gas meter #4



Site 413 - Photo 01 - Business (Family Dollar)



Site 413 - Photo 02 - Pole-mounted transformer





Site 413 - Photo 03 - Refridgeration unit #1



Site 413 - Photo 04 - Refridgeration unit #2



Site 414 - Photo 01 - Abandoned grocery store (Patel Brothers)




Site 414 - Photo 02 - Pole-mounted transformer





Site 415 - Photo 01 - Business (hair studio and check cashing)



Site 416 - Photo 01 - Restaurant (Domino's Pizza)




Site 416 - Photo 02 - Oil and water separator



Site 416 - Photo 03 - Oil and water separator manhole






Site 416 - Photo 04 - Pole-mounted transformer



Site 417 - Photo 01 - Restaurant and bakery



Site 417 - Photo 02 - Pole-mounted transformer #1



Site 417 - Photo 03 - Pole-mounted transformer #2





Site 418 - Photo 01 - Auto repair facility (Direct Auto Service)



Site 418 - Photo 02 - 200-gallon used oil AST



Site 418 - Photo 03 - 55-gallon drums of used anti-freeze



Site 418 - Photo 04 - Monitoring well





Site 419 - Photo 01 - Gas station and carwash



Site 419 - Photo 02 - UST tank field



Site 419 - Photo 03 - Vent pipes



Site 419 - Photo 04 - Carwash





Site 419 - Photo 05 - Possible oil and water separator



Site 419 - Photo 06 - Abandoned monitoring well



Site 420 - Photo 01 - Apartment buildings



Site 420 - Photo 02 - Pole-mounted transformer #1





Site 420 - Photo 03 - Pole-mounted transformer #2



Site 420 - Photo 04 - Natural gas meter #1



Site 420 - Photo 05 - Natural gas meter #2




Site 421 - Photo 01 - Restaurant (Burger King)





Site 421 - Photo 02 - Pole-mounted transformer



Site 422 - Photo 01 - Gas station (Citgo)



Site 422 - Photo 02 - UST tank field



Site 422 - Photo 03 - UST tank field label





Site 422 - Photo 04 - 200-gallon used oil AST



Site 422 - Photo 05 - 200-gallon kerosene AST



Site 422 - Photo 06 - Monitoring well



Site 423 - Photo 01 - Apartment buildings (Campus Gardens)





Site 423 - Photo 02 - Apartment buildings (Campus Gardens)



Site 423 - Photo 03 - Apartment buildings (Campus Gardens)



Site 423 - Photo 04 - Apartment buildings (Campus Gardens)



Site 423 - Photo 05 - Pole-mounted transformer #1





Site 423 - Photo 06 - Pole-mounted transformer #2



Site 423 - Photo 07 - Pole-mounted transformer #3



Site 423 - Photo 08 - Pole-mounted transformer #4



Site 423 - Photo 09 - Pole-mounted transformer #5





Site 423 - Photo 10 - Pole-mounted transformer #6



Site 423 - Photo 11 - Pole-mounted transformer #7



Site 423 - Photo 12 - Pole-mounted transformer #8



Site 423 - Photo 13 - Pole-mounted transformer #9





Site 423 - Photo 14 - Pole-mounted transformer #1



Site 423 - Photo 15 - Pole-mounted transformer #2



Site 423 - Photo 16 - Pool



Site 423 - Photo 17 - Pool house





Site 424 - Photo 01 - Auto repair facility (Just Tires)



Site 424 - Photo 02 - 200-gallon used oil AST



Site 424 - Photo 03 - 100-gallon used anti-freeze AST



Site 424 - Photo 04 - Floor drain





Site 424 - Photo 05 - Storage area #1 of 55-gallon drums of lube oil



Site 424 - Photo 06 - Storage area #2 of 55-gallon drums of lube oil



Site 424 - Photo 07 - Lube oil AST



Site 424 - Photo 08 - Oil and water separator





Site 425 - Photo 01 - Multiple businesses (restaurant, cleaner, and convenience store)



Site 425 - Photo 02 - Pole-mounted transformer



Site 425 - Photo 03 - 55-gallon drum of vegetable oil



Site 426 - Photo 01 - Overhead power line right of way





Site 427 - Photo 01 - Overhead power line right of way



Site 427 - Photo 02 - Cell phone tower



Site 427 - Photo 03 - Generator building at cell phone tower



Site 428 - Photo 01 - Gas station





Site 428 - Photo 02 - UST tank field



Site 428 - Photo 03 - Oil and water separator



Site 428 - Photo 04 - Abandoned monitoring well



Site 429 - Photo 01 - Restaurant (McDonalds)





Site 429 - Photo 02 - Parking lot



Site 429 - Photo 03 - Pole-mounted transformer



Site 430 - Photo 01 - Shopping center



Site 430 - Photo 02 - Pole-mounted transformer #1





Site 430 - Photo 03 - Pole-mounted transformer #2



Site 430 - Photo 04 - Shopping center refrigeration unit



Site 431 - Photo 01 - Gas station (Shell)



Site 431 - Photo 02 - UST tank field





Site 431 - Photo 03 - 300-gallon used oil AST



Site 431 - Photo 04 - 200-gallon lube oil AST



Site 431 - Photo 05 - Oil and water separator



Site 431 - Photo 06 - Restaurant and bar (King Kong)





Site 432 - Photo 01 - Business (Value Village)



Site 432 - Photo 02 - Parking lot



Site 432 - Photo 03 - Pole-mounted transformer



Site 433 - Photo 01 - Gas station





Site 433 - Photo 02 - Fueling UST tank field



Site 433 - Photo 03 - Used oil UST



Site 433 - Photo 04 - 55-gallon drums of used anti-freeze



Site 433 - Photo 05 - Oil and water separator





Site 433 - Photo 06 - Abandoned monitoring well



Site 434 - Photo 01 - Laundromat



Site 434 - Photo 02 - Pad-mounted transformer



Site 435 - Photo 01 - Residence






Site 436 - Photo 01 - Residence



Site 437 - Photo 01 - Residence



Site 438 - Photo 01 - Residence



Site 439 - Photo 01 - Residence





Site 440 - Photo 01 - Residence and hair salon



Site 440 - Photo 02 - Pole-mounted transformer



Site 441 - Photo 01 - Residence



Site 442 - Photo 01 - Residence





Site 443 - Photo 01 - Residence



Site 444 - Photo 01 - Residence



Site 445 - Photo 01 - Residence



Site 445 - Photo 02 - Pole-mounted transformer





Site 446 - Photo 01 - Residence



Site 447 - Photo 01 - Residence



Site 448 - Photo 01 - Shopping center



Site 448 - Photo 02 - Parking lot and shopping center





Site 448 - Photo 03 - Advance Auto Parts used oil AST



Site 448 - Photo 04 - Advance Auto Parts used oil AST fill pipe



Site 448 - Photo 05 - Advance Auto Parts used oil AST label



Site 448 - Photo 06 - Advanced Auto Parts used battery storage





Site 448 - Photo 07 - Pad-mounted transformer



Site 449 - Photo 01 - Residence



Site 449 - Photo 02 - Pole-mounted transformer



Site 450 - Photo 01 - Residence





Site 451 - Photo 01 - Residence



Site 452 - Photo 01 - Residence



Site 453 - Photo 01 - Residence



Site 454 - Photo 01 - Adelphi Manor archery range





Site 454 - Photo 02 - M-NCPPC Lane Manor park



Site 454 - Photo 03 - M-NCPPC Park



Site 454 - Photo 04 - Pole-mounted transformer



Site 455 - Photo 01 - Residence





Site 456 - Photo 01 - Residence



Site 457 - Photo 01 - Residence



Site 458 - Photo 01 - Residence



Site 459 - Photo 01 - Residence





Site 460 - Photo 01 - Residence



Site 460 - Photo 02 - Pole-mounted transformer



Site 461 - Photo 01 - Residence



Site 462 - Photo 01 - Residence





Site 463 - Photo 01 - Apartment buildings (Graduate Hills)



Site 463 - Photo 02 - Heating oil UST #1



Site 463 - Photo 03 - Sign at UST #1



Site 463 - Photo 04 - Heating oil UST #2





Site 463 - Photo 05 - Sign at UST #2



Site 463 - Photo 06 - Boiler room 1#



Site 463 - Photo 07 - Pad-mounted transformer #1



Site 463 - Photo 08 - Pad-mounted transformer #2





Site 463 - Photo 09 - Pad-mounted transformer #3



Site 463 - Photo 10 - Pad-mounted transformer #4



Site 463 - Photo 11 - Pole-mounted transformer



Site 463 - Photo 12 - Old appliances and metal debris





Site 463 - Photo 13 - HVAC #2



Site 463 - Photo 14 - Natural gas meter #1



Site 463 - Photo 15 - Natural gas meter #2



Site 464 - Photo 01 - Residence





Site 465 - Photo 01 - UMUC Parking lot



Site 465 - Photo 02 - UMUC Parking lot



Site 465 - Photo 03 - UMUC Parking lot



Site 466 - Photo 01 - University Baptist Church





Site 466 - Photo 02 - Pad-mounted transformer



Site 466 - Photo 03 - Base of communication tower #1



Site 466 - Photo 04 - Base of communication tower #2



Site 466 - Photo 05 - Communication towers





Site 466 - Photo 06 - Fence around communication tower #2



Site 466 - Photo 07 - Communication tower #2 Sign



Site 466 - Photo 08 - Natural gas meter



Site 467 - Photo 01 - Wooded lot





Site 467 - Photo 02 - Vacant lot



Site 468 - Photo 01 - University of Maryland



Site 468 - Photo 01 - University of Maryland parking lot



Site 468 - Photo 02 - Pad-mounted transformer





Site 468 - Photo 02 - University of Maryland



Site 468 - Photo 03 - Pole-mounted transformer



Site 468 - Photo 03 - University of Maryland



Site 469 - Photo 01 - University of Maryland





Site 469 - Photo 02 - University of Maryland



Site 469 - Photo 03 - University of Maryland



Site 469 - Photo 04 - University of Maryland



Site 469 - Photo 05 - University of Maryland





Site 470 - Photo 01 - Vacant lot



Site 470 - Photo 02 - Vacant lot



Site 470 - Photo 03 - Vacant lot



Site 470 - Photo 04 - Pad-mounted transformer





Site 471 - Photo 01 - Maryland Fire and Rescue Institute



Site 471 - Photo 02 - Maryland Fire and Rescue Institute



Site 471 - Photo 03 - MFRI parking area and training tower



Site 471 - Photo 04 - MFRI parking area





Site 471 - Photo 05 - Pad-mounted transformer



Site 472 - Photo 01 - Vacant lot



Site 472 - Photo 02 - UMD Physical Distribution Center



Site 473 - Photo 01 - Pad-mounted transformer





Site 474 - Photo 01 - Prince George's County flood control station



Site 474 - Photo 02 - Pad-mounted transformer at Prince George's County flood control station



Site 475 - Photo 01 - Vacant lot



Site 476 - Photo 01 - Vacant lot





Site 477 - Photo 01 - Prince George's County airport



Site 477 - Photo 02 - 10,000-gallon 100 octane fuel AST



Site 477 - Photo 03 - 10,000-gallon 100 octane fuel AST and dispenser




Site 477 - Photo 04 - 10,000-gallon 100 octane fuel AST label





Site 477 - Photo 05 - 500-gallon 100 octane fuel AST



Site 477 - Photo 06 - 500-gallon 100 octane fuel AST label



Site 477 - Photo 07 - 5,000-gallon jet fuel tanker truck



Site 477 - Photo 08 - 5,000-gallon jet fuel tanker truck





Site 477 - Photo 09 - Spill kit and fuel test drum



Site 477 - Photo 10 - 175-gallon used oil AST



Site 477 - Photo 11 - 30-gallon gas transfer tank



Site 477 - Photo 12 - Location of removed USTs





Site 477 - Photo 13 - Pad-mounted transformer



Site 477 - Photo 14 - Oil and water separator



Site 478 - Photo 01 - Abandoned Metro storage building



Site 478 - Photo 02 - Abandoned Metro storage building





Site 479 - Photo 01 - Grass lot adjacent to parking garage



Site 480 - Photo 01 - Parking garage



Site 480 - Photo 02 - Entrance to parking garage



Site 481 - Photo 01 - Auto repair facility (D&E Auto)





Site 481 - Photo 02 - Used oil AST



Site 481 - Photo 03 - Used oil and anti-freeze



Site 481 - Photo 04 - Drums of used anti-freeze



Site 481 - Photo 05 - Drums of used oil filters





Site 482 - Photo 01 - Business (Just Car Service)



Site 482 - Photo 03 - Used oil AST #1 (Just Car Service)




Site 482 - Photo 03 - Used oil AST #2 (Just Car Service)



Site 482 - Photo 04 - Used anti-freeze drum (Just Car Service)





Site 483 - Photo 01 - Parking lot



Site 483 - Photo 02 - Metro stop



Site 483 - Photo 03 - Metro stop



Site 483 - Photo 04 - Parking lot





Site 484 - Photo 01 - Wooded lot



Site 484 - Photo 02 - Pad-mounted transformer



Site 485 - Photo 01 - Metro Rail Line



Site 486 - Photo 01 - American Center of Physics entrance





Site 486 - Photo 02 - American Center of Physics entrance



Site 486 - Photo 03 - American Center of Physics entrance



Site 486 - Photo 04 - American Center of Physics building



Site 486 - Photo 05 - American Center of Physics building





Site 486 - Photo 06 - Wooded lot



Site 486 - Photo 07 - Emergency generator 2,500-gallon UST



Site 486 - Photo 08 - Emergency generator #2 UST spill bucket



Site 486 - Photo 09 - Emergency generator #1 AST





Site 486 - Photo 10 - Emergency generator #1 AST product lines



Site 486 - Photo 11 - Emergency generator #1 AST tank




Site 486 - Photo 12 - Emergency generator #1



Site 486 - Photo 13 - Emergency generator #1 AST spill bucket





Site 486 - Photo 14 - Emergency generator #1 AST labels



Site 486 - Photo 15 - Emergency generator #1 fuel filter



Site 486 - Photo 16 - Emergency generator #1 control panel



Site 486 - Photo 17 - Emergency generator #1 label





Site 486 - Photo 18 - Emergency generator #1 label



Site 486 - Photo 19 - Emergency generator #2



Site 486 - Photo 20 - Emergency generator #2 supply lines




Site 486 - Photo 21 - Emergency generator #2 UST vent pipe





Site 486 - Photo 22 - Emergency generator #2 label



Site 486 - Photo 23 - Emergency generator #2 label



Site 487 - Photo 01 - Wooded lot



Site 487 - Photo 02 - Wooded lot





Site 487 - Photo 03 - Wooded lot



Site 487 - Photo 04 - Wooded lot



Site 487 - Photo 05 - Pad-mounted transformers



Site 487 - Photo 06 - Pad-mounted transformers





Site 487 - Photo 07 - Pad-mounted transformer #1



Site 487 - Photo 08 - Pad-mounted transformer #2



Site 487 - Photo 09 - Pad-mounted transformer #3



Site 488 - Photo 01 - Wooded lot





Site 488 - Photo 02 - Pad-mounted transformer



Site 488 - Photo 03 - Verizon vault



Site 488 - Photo 04 - Verizon vault



Site 488 - Photo 05 - Storm water retention pond





Site 488 - Photo 06 - Wooded lot



Site 488 - Photo 07 - Parking lot



Site 488 - Photo 08 - Walking trail at public park



Site 488 - Photo 09 - Parking lot





Site 488 - Photo 10 - Parking lot



Site 488 - Photo 11 - Walking trail at public park



Site 489 - Photo 01 - Wooded lot



Site 490 - Photo 01 - Church





Site 490 - Photo 02 - Parking lot



Site 490 - Photo 03 - Parking lot



Site 490 - Photo 04 - Pad-mounted transformer



Site 491 - Photo 01 - Restaurant





Site 491 - Photo 02 - Pole-mounted transformer



Site 492 - Photo 01 - Bowling alley



Site 492 - Photo 02 - Pole-mounted transformer



Site 492 - Photo 03 - Pole-mounted transformer





Site 493 - Photo 01 - Multiple businesses (PG Brake, Bakery, and Tax Services)



Site 493 - Photo 02 - 200-gallon used oil AST



Site 493 - Photo 03 - Used anti-freeze drums (PG Brake)



Site 493 - Photo 04 - Pole-mounted transformer





Site 494 - Photo 01 - Tire shop



Site 494 - Photo 02 - Tire shop




Site 494 - Photo 03 - Pole-mounted transformer



Site 495 - Photo 01 - Shopping center





Site 495 - Photo 02 - Used oil AST



Site 495 - Photo 03 - Used oil AST



Site 495 - Photo 04 - Used batteries



Site 495 - Photo 05 - Pole-mounted transformer





Site 496 - Photo 01 - Auto repair facility (Total Auto)



Site 496 - Photo 02 - Used oil, anti-freeze, and lube oil AST



Site 496 - Photo 03 - Used anti-freeze drums and used batteries



Site 496 - Photo 04 - Lube oil ASTs





Site 496 - Photo 05 - Parts washer



Site 496 - Photo 06 - Oil and water separator



Site 497 - Photo 01 - Vacant Lot



Site 498 - Photo 01 - Residence





Site 498 - Photo 02 - Vacant lot



Site 499 - Photo 01 - Parking lot (Total Auto)



Site 499 - Photo 02 - Heating oil AST at adjacent property



Site 500 - Photo 01 - Restuarant (Wendy's)





Site 500 - Photo 02 - Parking lot



Site 500 - Photo 03 - Parking lot



Site 500 - Photo 04 - Parking lot



Site 500 - Photo 05 - Pole-mounted transformer





Site 501 - Photo 01 - Business (hair saslون)



Site 501 - Photo 02 - Pole-mounted transformer



Site 502 - Photo 01 - Residence



Site 503 - Photo 01 - Parking lot





Site 503 - Photo 02 - Vacant lot



Site 504 - Photo 01 - Business (Superior Tax and Mortgage)



Site 504 - Photo 02 - Vacant lot



Site 504 - Photo 03 - Pole-mounted transformer





Site 505 - Photo 01 - Restaurant (Boston Market) and pole-mounted transformer



Site 505 - Photo 02 - Pole-mounted transformer



Site 506 - Photo 01 - Gas station (Shell)



Site 506 - Photo 02 - UST tank field





Site 506 - Photo 03 - Used oil AST



Site 506 - Photo 04 - Surficial staining at used oil AST



Site 506 - Photo 05 - Heating oil AST



Site 506 - Photo 06 - Surficial staining at heating oil AST





Site 506 - Photo 07 - Used oil drums



Site 507 - Photo 01 - Office building (lawyer)



Site 508 - Photo 01 - Bank of America building



Site 508 - Photo 02 - Pole-mounted transformer





Site 509 - Photo 01 - St. Bernard's Church and School



Site 509 - Photo 02 - Pole-mounted transformer #1



Site 509 - Photo 03 - Pole-mounted transformer #2



Site 510 - Photo 01 - Wooded lot






Site 510 - Photo 02 - Wooded lot



Site 510 - Photo 03 - Wooded lot



Site 510 - Photo 04 - Wooded lot



Site 510 - Photo 05 - Wooded lot





Site 510 - Photo 06 - Wooded lot



Site 510 - Photo 07 - Dumping of construction debris in woods



Site 511 - Photo 01 - Office building



Site 511 - Photo 02 - Sign at office building





Site 511 - Photo 03 - Rear of office building



Site 511 - Photo 04 - Radio tower



Site 511 - Photo 05 - Pole-mounted transformer



Site 511 - Photo 06 - Pole-mounted transformer label





Site 512 - Photo 01 - Residence



Site 513 - Photo 01 - Residence



Site 514 - Photo 01 - Residence



Site 515 - Photo 01 - Residence





Site 516 - Photo 01 - Residence



Site 517 - Photo 01 - Residence



Site 518 - Photo 01 - Residence



Site 519 - Photo 01 - Residence





Site 520 - Photo 01 - Residence



Site 521 - Photo 01 - Residence



Site 522 - Photo 01 - Residence



Site 523 - Photo 01 - Residence





Site 524 - Photo 01 - Residence



Site 525 - Photo 01 - Residence



Site 526 - Photo 01 - Residence



Site 527 - Photo 01 - Residence





Site 528 - Photo 01 - Residence



Site 529 - Photo 01 - Residence



Site 530 - Photo 01 - Residence



Site 531 - Photo 01 - Residence





Site 532 - Photo 01 - Residence



Site 533 - Photo 01 - Dumping of old tires



Site 534 - Photo 01 - Pole-mounted transformer



Site 534 - Photo 01 - Residence





Site 536 - Photo 01 - Residence



Site 537 - Photo 01 - Residence



Site 538 - Photo 01 - Residence



Site 539 - Photo 01 - Residence






Site 540 - Photo 01 - Residence



Site 541 - Photo 01 - Residence



Site 542 - Photo 01 - Residence



Site 543 - Photo 01 - Gas station (Sunoco)






Site 543 - Photo 02 - Gas station (Sunoco)



Site 543 - Photo 03 - UST tank field



Site 543 - Photo 04 - Used oil AST



Site 543 - Photo 05 - Bulk motor oil storage





Site 543 - Photo 06 - Convenience store



Site 543 - Photo 07 - Laundromat and convenience store



Site 543 - Photo 08 - Pole-mounted transformer #1



Site 543 - Photo 09 - Pole-mounted transformer #2





Site 544 - Photo 01 - Shopping center



Site 544 - Photo 02 - Pad-mounted transformer



Site 544 - Photo 03 - Oil and water separator



Site 545 - Photo 01 - Gas station (Exxon)





Site 545 - Photo 02 - UST tank field



Site 545 - Photo 03 - Petroleum contact water drum



Site 545 - Photo 04 - Petroleum contact water drum label



Site 546 - Photo 01 - Apartment buildings (Prince Georgetown)





Site 546 - Photo 02 - Pad-mounted transformer #1



Site 546 - Photo 03 - Pad-mounted transformer #2



Site 546 - Photo 04 - Pad-mounted transformer #3



Site 546 - Photo 05 - Pad-mounted transformer #4





Site 546 - Photo 06 - Pad-mounted transformer #5



Site 547 - Photo 01 - MD National Capital Park Police



Site 547 - Photo 02 - MD National Capital Park Police



Site 547 - Photo 03 - MD National Capital Park Police





Site 547 - Photo 04 - MD National Capital Park Police



Site 547 - Photo 05 - UST tank field



Site 547 - Photo 06 - UST tank field



Site 547 - Photo 07 - Lube oil and used oil containers





Site 547 - Photo 08 - Diesel generator



Site 547 - Photo 09 - Location of removed leaking UST



Site 547 - Photo 10 - 150-gallon emergency generator AST for cell tower



Site 547 - Photo 11 - 150-gallon emergency generator AST vent and fill pipe at cell tower





Site 547 - Photo 12 - Cell tower sign



Site 547 - Photo 13 - Natural gas generator



Site 548 - Photo 01 - Apartment buildings (East Pines)



Site 548 - Photo 02 - Apartment building (East Pines)





Site 548 - Photo 03 - Pole-mounted transformers #1



Site 548 - Photo 04 - Pole-mounted transformers #2



Site 548 - Photo 05 - Pole-mounted transformers #3



Site 549 - Photo 01 - Residence





Site 550 - Photo 01 - Residence



Site 551 - Photo 01 - Residence and vacant lot



Site 552 - Photo 01 - Wooded lot and traffic signal box



Site 552 - Photo 02 - Wooded lot





Site 553 - Photo 01 - Apartment buildings (New Carrollton)



Site 553 - Photo 02 - Pad-mounted transformer #1



Site 553 - Photo 03 - Pad-mounted transformer #2



Site 553 - Photo 04 - Pad-mounted transformer #3





Site 553 - Photo 05 - Pad-mounted transformer #4



Site 555 - Photo 01 - ASTs and fuel dispensers



Site 555 - Photo 02 - 10,000-gallon gasoline AST



Site 555 - Photo 03 - 5,000-gallon diesel AST





Site 555 - Photo 04 - Used oil AST and lube oil drums



Site 555 - Photo 05 - Lube oil drums



Site 555 - Photo 06 - Lube oil drums



Site 555 - Photo 07 - Pad-mounted transformer





Site 555 - Photo 08 - Propane AST



Site 555 - Photo 09 - Glenridge Community Park



Site 555 - Photo 10 - Wooded Area



Site 556 - Photo 01 - Glenridge Elementary School





Site 556 - Photo 02 - Glenridge Elementary School



Site 556 - Photo 03 - 10,000-gallon heating oil UST



Site 556 - Photo 04 - UST vent pipe



Site 556 - Photo 05 - AST for boiler





Site 556 - Photo 06 - Boiler



Site 556 - Photo 07 - Boiler




Site 556 - Photo 08 - Boiler fuel pump



Site 556 - Photo 09 - Boiler





Site 556 - Photo 10 - Boiler label



Site 556 - Photo 11 - Natural gas generator



Site 556 - Photo 12 - Natural gas meter



Site 557 - Photo 01 - Parking lot and shopping center





Site 557 - Photo 02 - Parking lot and shopping center



Site 557 - Photo 03 - Doctors office



Site 557 - Photo 04 - Dry cleaning facility



Site 557 - Photo 05 - Parking lot





Site 557 - Photo 06 - Pad-mounted transformers



Site 557 - Photo 07 - Pad-mounted transformer #1



Site 557 - Photo 08 - Pad-mounted transformer #2



Site 557 - Photo 09 - Pole-mounted tranformer #1





Site 557 - Photo 10 - Pole-mounted tranformer #2



Site 557 - Photo 11 - Oil and water separator



Site 557 - Photo 12 - Natural Gas Hook-up



Site 558 - Photo 01 - Dulce Vida Bakery





Site 558 - Photo 02 - Bakery (Dulce Vida)



Site 558 - Photo 03 - Pole-mounted transformer



Site 558 - Photo 04 - Unknown vault



Site 558 - Photo 05 - Vegetable oil drum





Site 558 - Photo 06 - Dumpster and drum storage



Site 558 - Photo 07 - Natural gas connection



Site 559 - Photo 01 - Bank of America



Site 559 - Photo 02 - Natural gas meter





Site 560 - Photo 01 - Office building



Site 560 - Photo 02 - Natural gas meter



Site 560 - Photo 03 - Pole-mounted transformer



Site 560 - Photo 04 - Sign at building





Site 561 - Photo 01 - Parking lot



Site 561 - Photo 02 - Bank drive-thru (Bank of America)



Site 562 - Photo 01 - Wooded lot



Site 563 - Photo 01 - Apartment buildings (Chesapeake Landing)





Site 563 - Photo 02 - Pad-mounted transformer #1



Site 563 - Photo 03 - Pad-mounted transformer #2



Site 563 - Photo 04 - Pad-mounted transformer #3



Site 563 - Photo 05 - Pad-mounted transformer #4





Site 563 - Photo 06 - Pad-mounted transformer #5



Site 564 - Photo 01 - View of stream channel



Site 564 - Photo 02 - View of stream channel



Site 564 - Photo 03 - Pad-mounted transformer





Site 565 - Photo 01 - View of stream channel



Site 565 - Photo 02 - View of stream channel



Site 565 - Photo 03 - View of stream channel



Site 565 - Photo 04 - View of stream channel





Site 565 - Photo 05 - View of stream channel



Site 565 - Photo 06 - View of stream channel



Site 565 - Photo 07 - View of stream channel



Site 566 - Photo 01 - View of stream channel





Site 566 - Photo 02 - View of stream channel



Site 566 - Photo 03 - View of stream channel



Site 566 - Photo 04 - View of stream channel



Site 566 - Photo 05 - View of stream channel





Site 566 - Photo 06 - View of stream channel



Site 566 - Photo 07 - View of stream channel



Site 566 - Photo 08 - View of stream channel



Site 566 - Photo 09 - Outfall





Site 567 - Photo 01 - Outfall



Site 567 - Photo 02 - Outfall



Site 567 - Photo 03 - Outfall



Site 567 - Photo 04 - Vacant Lot





Site 568 - Photo 01 - Entrance to vacant lot



Site 568 - Photo 02 - Roadside debris



Site 568 - Photo 03 - Vacant lot



Site 569 - Photo 01 - Entrance to PEPCO substation





Site 569 - Photo 02 - Transformers at PEPCO substation



Site 569 - Photo 03 - Transformers at PEPCO substation



Site 569 - Photo 04 - PEPCO substation



Site 569 - Photo 05 - Entrance to New Carrollton Metro Station





Site 570 - Photo 01 - Access road to railroad tracks



Site 570 - Photo 02 - Access road to railroad tracks



Site 570 - Photo 03 - Access road to railroad tracks



Site 571 - Photo 01 - New Carrollton Metro Station






Site 571 - Photo 02 - New Carrollton Metro Station



Site 571 - Photo 03 - Pad-mounted transformer



Site 571 - Photo 04 - Pad-mounted transformers



Site 572 - Photo 01 - Parking lot at New Carrollton Metro Station





Site 572 - Photo 02 - Parking lot at New Carrollton Metro Station



Site 572 - Photo 02 - Railroad tracks



Site 572 - Photo 03 - Parking lot at New Carrollton Metro Station



Site 572 - Photo 04 - Parking lot at New Carrollton Metro Station






Site 572 - Photo 05 - Parking lot at New Carrollton Metro Station



Site 572 - Photo 06 - Parking lot at New Carrollton Metro Station



Site 572 - Photo 07 - Entrance to New Carrollton parking lot



Site 572 - Photo 08 - Entrance to New Carrollton parking lot






Site 572 - Photo 09 - Parking lot at New Carrollton Metro Station



Site 572 - Photo 10 - Parking lot at New Carrollton Metro Station



Site 572 - Photo 11 - Parking lot at New Carrollton Metro Station



Site 572 - Photo 12 - Parking lot at New Carrollton Metro Station





Site 572 - Photo 13 - Parking lot at New Carrollton Metro Station



Site 572 - Photo 14 - Parking lot at New Carrollton Metro Station



Site 573 - Photo 01 - Railroad tracks